

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2020

Submitted Date:

05/06/2020

Document Number:

699700132

### FIELD INSPECTION FORM

Loc ID 316579 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10384  
Name of Operator: GENESIS GAS & OIL COLORADO LLC  
Address: 900 NE LOOP 410 STE D211  
City: SAN ANTONIO State: TX Zip: 78209

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 2 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kimmel, March	210-363-2859	mkimmel@genesishgoco.com	
Fischer, Alex		alex.fischer@state.co.us	
Lutz, Deborah		debbie.lutz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286506	WELL	SI	05/14/2013	GW	103-10893	FLETCHER GULCH 3-22	EI

**General Comment:**

On April 30, 2020, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of GENESIS GAS & OIL COLORADO LLC (Genesis, operator #10384) FLETCHER GULCH 3-22 location ID 316579.

COGCC staff observed a compressor station located approximately 200 feet south of the FLETCHER GULCH 3-22 location.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Compressor		
Comment:	The operator is not in compliance with Rule 313.B. Within 72-hours of receiving this Field Inspection Report, contact Debbie Lutz (303-894-2100 X 5185 or debbie.lutz@state.co.us ) regarding the Form 12 and compliance with Rule 313.B.	
Corrective Action:	Within 14-days of receiving this Field Inspection Report, the operator shall bring this compressor station into compliance per Rule 313.B., notifying Debbie Lutz, Alex Fischer, and John Heil when the Form 12 has been submitted.	Date: <u>05/20/2020</u>

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 286506 Type: WELL API Number: 103-10893 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402391913	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143941">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143941</a>
699700133	20200430 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143940">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143940</a>