

Inspection Photos

Location Name: LARAMIE ENERGY LLC Griffith /11-2 Pad

Location ID: 334445



Photo #1160 from SW corner of location



Photo #1160 Unused equipment on separator.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Griffith /11-2 Pad

Location ID: 334445



Photo #1162 Trash inside tank containment.




Photo #1163 Trash inside tank containment.