

Inspection Photos
 Location Name: Po 12-12
 Location ID: 313081

Click here to reset the form
 State of Colorado
 Oil and Gas Conservation Commission

FORM 21 (Rev. 07/14)

MECHANICAL INTEGRITY TEST

OSCC Question Number: 0000

Operator: SOUTHLAND ROYALTY COMPANY LLC
 Address: 400 W 7TH ST
 City: FORT WORTH, STATE: TX, ZIP: 76102
 API Number: 02-001-00058
 Well/Property Name: PO 12-12

Contract Name and Telephone: DANNY GALLERBECK
 Phone: (817) 365-6632

Well Type: SHUT-IN PRODUCTION WELL INJECTION WELL

Test Type: Test to Maintain R/TA status > year LIC Recirc Packer
 Verification of Packers Annual LIC Test

Wellbore Data at Time of Test
 Fractured Interval: 5914-5946
 Casing Depth: 2,075
 Tubing Depth: 5,064
 7th Packer Depth: 5,829

Engine	Wellbore Being Test	Casing Pressure (PSI)	Wellbore Pressure (PSI)	Wellbore Pressure (PSI)
330 PSI	770 PSI	330 PSI	770 PSI	760 PSI

Test Witnessed by State Representative? Yes
 OSCC Field Representative (Print Name): Emily Waldron

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

OSCC Inspector: [Signature] Title: Field Inspector Date: 5/12/20

Handwritten note: We were unable to bleed off pressure without venting to atmosphere. Inspector unable to reach engineer, well was left w/ 770 PSI on tubing and 330 PSI on casing.

Photo 1. Photo of Form 21 as filled out and signed in the field.