

Inspection Photos  
Operator: BP America  
API#: 067-07057  
Date: 5/12/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome and sandberg bluegrass.





Photo 3. View of the northwestern project area from the northern corner facing southeastward.





Photo 4. View of reference area vegetation comprised of ponderosa pine forest with herbaceous understory with grasses such as western wheatgrass and Arizona fescue.