

Inspection Photos  
Operator: BP America  
API#: 067-07332  
Date: 5/12/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing with grasses such as smooth brome and western wheatgrass.



Photo 3. View of the western project area from the northwestern corner facing eastward. Revegetation is progressing with blue flax.



Photo 4. View of reference area vegetation comprised of ponderosa pine forest with herbaceous understory with grasses such as western wheatgrass and Arizona fescue.