

Inspection Photos
Operator: BP America
API#: 067-08637
Date: 5/12/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome, and western wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photos 4/5. View of Canada thistles observed within the eastern project area. Approximately 200 individuals observed.



Photo 6. View of reference area vegetation comprised of ponderosa pine woodland with herbaceous understory with grasses such as western wheatgrass and muttongrass and shrubs such as gambel oak and antelope bitterbrush.