

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/13/2020

Document Number:

699601035

**FIELD INSPECTION FORM**

Loc ID 314061 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 66190  
Name of Operator: OMIMEX PETROLEUM INC  
Address: 7950 JOHN T WHITE ROAD  
City: FORT WORTH State: TX Zip: 76120

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292756	WELL	PR	02/21/2008	GW	095-06152	MAILANDER 6-34-6-45	PR

**General Comment:**

Routine FIR - SATISFACTORY

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track grassland		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	# 0		corrective date
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 292756 Type: WELL API Number: 095-06152 Status: PR Insp. Status: PR

**Producing Well**

Comment: NG

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT