

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Colorado Oil and Gas Conservation Commission
40.3579, -104.72223, 1401.7m, 255°
May 13, 2020 14:11:06

Photo 1: Tank Battery Sign; reflects current operator



Colorado Oil and Gas Conservation Commission
40.35792, -104.72227, 1402.4m, 154°
May 13, 2020 14:11:20

Photo 2: Tank Battery

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 3: PA wellhead location



Photo 4: Separator anchored

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 5: Unused equipment



Photo 6: Unused equipment

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 7: Debris near separator



Photo 8: Debris near gas meter

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 9: Trash



Photo 10: Trash