

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/13/2020

Document Number:

679602643

FIELD INSPECTION FORM

Loc ID 330030 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
,		dnr_cogccengineering@state. co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250429	WELL	SI	02/01/2019	GW	123-18232	CAVANAGH 36-10H6	PA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	OTHER			
Comment:	Access Road: Adequate			
Corrective Action:			Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 95%;" type="text"/>
Corrective Action:	<input style="width: 95%;" type="text"/>		

Good Housekeeping:

Type	UNUSED EQUIPMENT			
Comment:	Disconnected/unused gas meter. See attached photo.			
Corrective Action:	Comply with Rule 603.f.		Date:	11/26/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	Gas Meter Run	# 1			corrective date
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities

Facility ID: 250429 Type: WELL API Number: 123-18232 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA; FORM 42 DOC#: 402132842 IN WELLFILE.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679601415 All corrective actions assigned in previous inspection DOC#: 679601415 has not been resolved. Previous corrective action has been reassigned with its original corrective action date. No new corrective actions were observed at the time of re-inspection. Review my inspection, photos and previous inspection DOC#: 679601415 for additional information on this location.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Wednesday, May 13, 2020 at approximately 15:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at CAVANAGH 36-10H6 (Noble Energy), at location #: 330030 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. Unused/disconnected gas meter. REMOVE TO COMPLY WITH RULE 603.F. (Corrective Action Date: November 26, 2019) See attached photo #1.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	05/13/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602644	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5149634