

Inspection Photos
Location Name: ANKENEY /2-28 Pad
Location #: 323296



Photo #1
Ankeney 2-28 (05-123-12829) Wellsite
Plugged & Abandoned | PA
~ 15 yds.
Reclamation progressing



Photo #2
Ankeney 2-28 Battery site
Abandoned: ALL Equipment removed
Reclamation progressing

Inspection Photos
Location Name: ANKENEY /2-28 Pad
Location #: 323296



Photo #3
Ankeney 2-28 Battery site
*Inadequate berm height
prior insp.*



Photo #4
Ankeney 2-28 Battery site
Abandoned: ALL Equipment removed
*Reclamation progressing
Corrective Action mitigated*

Inspection Photos
Location Name: ANKENEY /2-28 Pad
Location #: 323296



Photo #5
Ankeney 2-28 Battery site
*Weeds at tank site
prior insp.*



Photo #6
Ankeney 2-28 Battery site
Abandoned: ALL Equipment removed
Reclamation progressing
Corrective Action mitigated

Inspection Photos
Location Name: ANKENEY /2-28 Pad
Location #: 323296



Photo #7
Ankeney 2-28 Battery site
*Weeds at separator
prior insp.*



Photo #8
Ankeney 2-28 Battery site
Abandoned: ALL Equipment removed
*Reclamation progressing
Corrective Action mitigated*

Inspection Photos
Location Name: ANKENEY /2-28 Pad
Location #: 323296



Photo #9
Ankeney 2-28 Wellsite
*Unused Equipment (well parts)
prior insp.*



Photo #10
Ankeney 2-28 Wellsite
Plugged & Abandoned | PA
ALL Equipment removed
Corrective Action mitigated

Inspection Photos
Location Name: ANKENEY /2-28 Pad
Location #: 323296



Photo #11
Ankeney 2-28 Wellsite
Unmarked risers
prior insp.



Photo #12
Ankeney 2-28 Wellsite
Plugged & Abandoned | PA
ALL Equipment removed
Corrective Action mitigated