


**Inspection Photos**  
**Location Name: PA 21 – 2**  
**Location ID: 334767 & Spill/Release ID: 443563**  
**Inspection Date: May 5, 2020**



**Location sign**



**Tank facility sign**



**Inspection Photos**

**Location Name: PA 21 – 2**

**Location ID: 334767 & Spill/Release ID: 443563**

**Inspection Date: May 5, 2020**



**View of the combustor where Spill/Release ID 443563 occurred**



**PA 21 – 2 location north of the combustor**



**Inspection Photos**

**Location Name: PA 21 – 2**

**Location ID: 334767 & Spill/Release ID: 443563**

**Inspection Date: May 5, 2020**



**Trough containing fluids with a detectable hydrocarbon odor**



**Trough containing fluids with a detectable hydrocarbon odor**



**Inspection Photos**

**Location Name: PA 21 – 2**

**Location ID: 334767 & Spill/Release ID: 443563**

**Inspection Date: May 5, 2020**



**Five gallon bucket containing fluids with a detectable hydrocarbon odor**



**Repairs made to the PA 21 – 2 tank battery secondary containment**

