

Inspection Photos

5/13/2020

Operator: D & D RESOURCES INC # 22315

Location ID: 315255

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: D & D RESOURCES INC # 22315
Location ID: 315255



Photo 1: Photo taken from the well facing north. Photo shows well marker and the oil and gas associated utility equipment remaining on the Location.



Photo 2: Photo taken from the north end of the location, facing west. Photo shows areas where stained soils were observed; area remains bare and unvegetated.

Inspection Photos
Operator Name: D & D RESOURCES INC # 22315
Location ID: 315255



Photo 3: Photo taken from the north end of the location, facing west. Photo shows areas where stained soils were observed; area remains bare and unvegetated.