

# Inspection Photos

5/13/2020

Operator: EAGLE OPERATING INC - 26155

Location ID: 316345

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 1:** Photo taken from the northeast end of the location, facing southwest. Photo shows additional reclamation activities appear to have been conducted per corrective actions.



**Photo 2:** Photo taken from the northeast end of the location, facing west. Photo shows additional reclamation activities appear to have been conducted per corrective actions.

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 3:** Photo taken from the southwest corner of the Location, facing north. Photos 3-5 provide an overview of the Location from north, northeast to east. Photos show additional reclamation activities appear to have been conducted per corrective actions.

**Photo 4:** See comments under photo 3.

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 5:** See comments under photo 3.



**Photo 6:** Photo taken from the southeast end of the Location. Photo shows erosion degradation due to stormwater runoff from the Location is evident.

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 7:** Continued from photo 6. Photo shows erosion degradation and sediment transport off site due to stormwater runoff from the location.



**Photo 8:** See comments under photo 6.

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 9:** See comments under photo 6.



**Photo 10:** Photo taken from the north end of the location, facing west. Photo of Germination transect/survey #1.

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 11:** Photo taken from the central areas of the location, facing west. Photo of Germination transect/survey #2.



**Photo 12:** Photo taken from the central areas of the location, facing south. Photo of Germination transect/survey #3.

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 316345



**Photo 13:** Photo taken the Location, facing north. Photo shows vegetation establishing on Location is predominantly undesirable weedy plant species such as Cheat grass.

**Photo 14:** Continued from photo 13.