

Final Reclamation Inspection

May 12, 2020

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06159

Inspection Document #: 697501505

Larimer County, CO

SWNW Section 31 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PROCTOR-SKAER #1-A
API: 05-069-06159



Photo 1. Photo taken on January 8, 2018 from the well location, facing North. Operator is IN-PROCESS of reclamation activities regarding the previous corrective action inspection. A follow-up inspection will occur at a future date to ensure compliance with Rule 1004 standards.



Photo 2. Photo taken on May 17, 2018 from the well location, facing North. Germination evident throughout the entire well location. A follow-up inspection will occur at a future date to ensure compliance with Rule 1004 standards.

Inspection Photos
Location Name: PROCTOR-SKAER #1-A
API: 05-069-06159



Photo 3. Photo taken on May 12, 2020 from the well location, facing East. Photo illustrates the establishment of desirable species (Smooth brome) which is reflective of reference area vegetative levels.



Photo 4. Photo taken on May 12, 2020 from the well location, facing North. See comments under Photo 3. Note: the large robust plants in the photo are *Rumex sp.* which was observed in reference areas and is not a noxious weed.

Inspection Photos
Location Name: PROCTOR-SKAER #1-A
API: 05-069-06159



Photo 5. Reference photo taken on May 12, 2020 east of the well location, facing East. Photo illustrates the well location is reflective of reference area vegetative levels.



Photo 6. Photo taken on May 12, 2020 from the associated offsite tank battery location, facing East. Photo illustrates a final land use change and the location is now part of a horse arena.