

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/13/2020

Document Number:

701000706

**FIELD INSPECTION FORM**

Loc ID 321603 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10713  
Name of Operator: DARRAH OIL COMPANY LLC  
Address: 125 N MARKET STE 1425  
City: WICHITA State: KS Zip: 67202

**Findings:**

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone          | Email                        | Comment                         |
|-----------------|----------------|------------------------------|---------------------------------|
| Shalberg, Greg  | 719-688-3547   | gregshalberg@aol.com         | <a href="#">all inspections</a> |
| Atterbury, Mike | (316) 219-3390 | mike.atterbury@darrahoil.com |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 207461      | WELL | PR     | 10/03/1983  | OW         | 017-06396 | CHAMPLIN 205 AMOCO A 2 | PR          |

**General Comment:**

[Routine Inspection](#)

| Location   |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   | Gravel road through pasture  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Lease sign by unit   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | BATTERY  |        |                 |
| Comment:   | Lease sign at tank battery   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | TANK LABELS/PLACARDS   |        |                 |
| Comment:   | Stickers on tanks  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| <b>Emergency Contact Number:</b>                       |  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date: _____     |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Fencing/:</b>                                       |  |        |                 |
| Type   | PUMP JACK  |        |                 |
| Comment:   | Location is 3/4 fenced with wire   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Pump Jack  | # 1  |        | corrective date |
| Comment:   | Lufkin 320   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Ancillary equipment                              | # 6  |        |                 |
| Comment:   | Electric panel, cathodic rectifier on REA pole (on wellhead location), propane tank for horizontal treater, electric panel, phase convertor and cathodic rectifier on REA pole at tank battery |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Prime Mover                                      | # 1  |        |                 |
| Comment:   | Electric motor   |        |                 |

|                                 |   |       |  |
|---------------------------------|---|-------|--|
| Corrective Action:              |   | Date: |  |
| Type: FWKO                      | # 1   |       |  |
| Comment:                        | FWKO on west side of vertical treater                               |       |  |
| Corrective Action:              |   | Date: |  |
| Type: Deadman # & Marked        | # 4   |       |  |
| Comment:                        |   |       |  |
| Corrective Action:              |   | Date: |  |
| Type: Horizontal Heater Treater | # 1   |       |  |
| Comment:                        | Treater on east side of vertical treater                            |       |  |
| Corrective Action:              |   | Date: |  |
| Type: Vertical Heater Treater   | # 1   |       |  |
| Comment:                        | Vertical heater treater is not in use and stored neatly on location |       |  |
| Corrective Action:              |   | Date: |  |

**Tanks and Berms:**

| Contents           | #   | Capacity | Type           | Tank ID | SE GPS                |
|--------------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER     | 1   | 300 BBLs | FIBERGLASS AST |         | 38.723500,-102.533240 |
| Comment:           | Tan water tank is on east side of oil tanks |          |                |         |                       |
| Corrective Action: |   |          |                |         | Date:                 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity     | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------|---------------------|---------------------|-------------|
|                    |              |                     |                     |             |
| Comment:           | Shared berms |                     |                     |             |
| Corrective Action: |              |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 2 | 300 BBLs | STEEL AST |         | 38.723500,-102.533240 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 207461 Type: WELL API Number: 017-06396 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for \(Chaplin 205 Amoco A-2, A-4, A-5\) 1630' S](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT