

Inspection Photos
Location Name: Carlson 42-33 1
Location ID: 320044



Pic 1

Pic 2 chemical tote with no BMP

Inspection Photos
Location Name: Carlson 42-33 1
Location ID: 320044



Pic 3 lid on tote open to atmosphere



Pic 4

Inspection Photos
Location Name: Carlson 42-33 1
Location ID: 320044



Pic 5



Pic 6 mechanical issue with tank/stained soil

Inspection Photos
Location Name: Carlson 42-33 1
Location ID: 320044



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.83478, -104.54738, 5315.4ft, 96°
05/14/2020 13:44:33



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.83484, -104.54718, 5330.9ft, 104°
05/14/2020 13:44:49

Pic 7

Pic 8

Inspection Photos
Location Name: Carlson 42-33 1
Location ID: 320044



Pic 9

Pic 10 trash inside separator house

Inspection Photos
Location Name: Carlson 42-33 1
Location ID: 320044



Pic 11 trash inside separator house