



**JOB DATA SHEET**

Company NOBLE ENERGY Well Name and No. FURROW USX AB 15-05P Engineer ADAM KERR  
 County WELD Date 9/18/2019 Ticket No. 3814-0226 Unit No. 3814  
 District Odessa TX 0915-200 Line Size \_\_\_\_\_ 0 Line Length \_\_\_\_\_ 0  
 Job Time: 7:00 AM Shop Time: 6:00 AM Leave Shop: 6:25 AM Arrive Location: 6:50 AM  
 Field Hrs. 3:10:00 Standby Hours: 0:00:00 Total Hours 4:05:00 Travel Time Hrs. 0:55:00  
 Trip Miles 28 Leave Location: 3:50 PM Arrive Shop: 4:20 PM

**Notice: Engineer to monitor for stray voltage prior to rig up:** Wellhead volts: 0 Rig volts : 0

Were there any equipment or down hole failures? Yes \_\_\_\_\_ No X If yes explain on Quality Control Analysis Form  
 Were there any hot shots required? Yes \_\_\_\_\_ No X If yes explain on Quality Control Analysis Form  
 Were there any personnel problems? Yes \_\_\_\_\_ No X If yes explain on Quality Control Analysis Form  
 Were there any accidents? Yes \_\_\_\_\_ No X If yes explain on Quality Control Analysis Form  
 Were there any near misses? Yes \_\_\_\_\_ No X If yes explain on Quality Control Analysis Form

**Well Information**

Casing Size 5.5" Liner Size \_\_\_\_\_ Tubing Size \_\_\_\_\_ 0 Drill Pipe Size \_\_\_\_\_  
 Drill Collar \_\_\_\_\_ Minimum I.D. \_\_\_\_\_ Fluid Level \_\_\_\_\_ 0 Deviation \_\_\_\_\_  
 Max. Temp. 275\* Max. Pressure \_\_\_\_\_

**Run Data**

**RUN INFORMATION**

**\*\*\*\*\*REMARKS SECTION\*\*\*\*\*DESCRIBE RUN DETAILS IN FULL \*\*\*\*\***

|           |                       |     |                 |  |
|-----------|-----------------------|-----|-----------------|--|
| 1 Time in | <u>12:05 PM</u>       | Out | <u>1:20 PM</u>  | RIH WITH CIBP FOR 5.5" CASING, SET CIBP @ 6,718' |
| From      | <u>SURFACE</u>        | To  | <u>6,718'</u>   |  |
| Service   | <u>SET CIBP</u>       |     |                 | <u>POOH</u>                                      |
| 2 Time in | <u>1:30 PM</u>        | Out | <u>2:15 PM</u>  | RIH WITH DUMPBAILER, DUMPBAILED 2SXS @ 6,718'    |
| From      | <u>SURFACE</u>        | To  | <u>6,718'</u>   |  |
| Service   | <u>DUMPBAIL 2 SXS</u> |     |                 | <u>POOH</u>                                      |
| 3 Time in | <u>2:35 PM</u>        | Out | <u>3:00 PM</u>  | RIH WITH 6SPF SQUEEZE GUN, PERF @ 2,280'         |
| From      | <u>SURFACE</u>        | To  | <u>2,280'</u>   |  |
| Service   | <u>6SPF PERF</u>      |     |                 | <u>POOH</u>                                      |
| 4 Time in | <u>3:15 PM</u>        | Out | <u>3:30 PM</u>  | RIH WITH 6SPF SQUEEZE GUN, PERF @ 1,780'         |
| From      | <u>SURFACE</u>        | To  | <u>1,780'</u>   |  |
| Service   | <u>6SPF PERF</u>      |     |                 | <u>POOH</u>                                      |
| 5 Time in | <u>12:00 AM</u>       | Out | <u>12:00 AM</u> |  |
| From      | <u>0</u>              | To  | <u>0</u>        |  |
| Service   | <u>0</u>              |     |                 |  |
| 6 Time in |                       | Out |                 |  |
| From      |                       | To  |                 |  |
| Service   |                       |     |                 |  |
| 7 Time in |                       | Out |                 |  |
| From      |                       | To  |                 |  |
| Service   |                       |     |                 |  |
| 8 Time in |                       | Out |                 |  |
| From      |                       | To  |                 |  |
| Service   |                       |     |                 |  |



# Well Services

E - LINE

## JOB DATA SHEET

Company NOBLE ENERGY Well Name and No. FURROW USX AB 15-05P Engineer ADAM KERR  
 County WELD Date 9/19/2019 Ticket No. 3814-0227 Unit No. 3814  
 District Odessa TX 0915-200 Line Size 0 Line Length 0  
 Job Time: 2:00 PM Shop Time: 7:00 AM Leave Shop: 1:00 PM Arrive Location: 1:30 PM  
 Field Hrs. 1:00:00 Standby Hours: 0:00:00 Total Hours 2:00:00 Travel Time Hrs. 1:00:00  
 Trip Miles 28 Leave Location: 3:25 PM Arrive Shop: 3:55 PM

**Notice: Engineer to monitor for stray voltage prior to rig up: Wellhead volts: 0 Rig volts : 0**

Were there any equipment or down hole failures? Yes      No X If yes explain on Quality Control Analysis Form  
 Were there any hot shots required? Yes      No X If yes explain on Quality Control Analysis Form  
 Were there any personnel problems? Yes      No X If yes explain on Quality Control Analysis Form  
 Were there any accidents? Yes      No X If yes explain on Quality Control Analysis Form  
 Were there any near misses? Yes      No X If yes explain on Quality Control Analysis Form

### Well Information

Casing Size 5.5" Liner Size      Tubing Size 0 Drill Pipe Size       
 Drill Collar      Minimum I.D.      Fluid Level 0 Deviation       
 Max. Temp. 275\* Max. Pressure     

### Run Data

#### RUN INFORMATION

\*\*\*\*\*REMARKS SECTION\*\*\*\*\*DESCRIBE RUN DETAILS IN FULL\*\*\*\*\*

|           |                  |     |                 |  |
|-----------|------------------|-----|-----------------|--|
| 1 Time in | <u>2:40 PM</u>   | Out | <u>3:10 PM</u>  | <u>RIH WITH 6SPF SQUEEZE GUN, PERF @ 988'</u><br><u>POOH</u> |
| From      | <u>SURFACE</u>   | To  | <u>988'</u>     |  |
| Service   | <u>6SPF PERF</u> |     |                 |  |
| 2 Time in | <u>12:00 AM</u>  | Out | <u>12:00 AM</u> |  |
| From      | <u>0</u>         | To  | <u>0</u>        |  |
| Service   | <u>0</u>         |     |                 |  |
| 3 Time in | <u>12:00 AM</u>  | Out | <u>12:00 AM</u> |  |
| From      | <u>0</u>         | To  | <u>0</u>        |  |
| Service   | <u>0</u>         |     |                 |  |
| 4 Time in | <u>12:00 AM</u>  | Out | <u>12:00 AM</u> |  |
| From      | <u>0</u>         | To  | <u>0</u>        |  |
| Service   | <u>0</u>         |     |                 |  |
| 5 Time in | <u>12:00 AM</u>  | Out | <u>12:00 AM</u> |  |
| From      | <u>0</u>         | To  | <u>0</u>        |  |
| Service   | <u>0</u>         |     |                 |  |
| 6 Time in | <u>    </u>      | Out | <u>    </u>     |  |
| From      | <u>    </u>      | To  | <u>    </u>     |  |
| Service   | <u>    </u>      |     |                 |  |
| 7 Time in | <u>    </u>      | Out | <u>    </u>     |  |
| From      | <u>    </u>      | To  | <u>    </u>     |  |
| Service   | <u>    </u>      |     |                 |  |
| 8 Time in | <u>    </u>      | Out | <u>    </u>     |  |
| From      | <u>    </u>      | To  | <u>    </u>     |  |
| Service   | <u>    </u>      |     |                 |  |