

Location Name: – Ward and Son Operating - Loc ID 311869

Inspection Date: 05/06/2020



Photo # 1 –

Location Name: – Ward and Son Operating - Loc ID 311869

Inspection Date: 05/06/2020



Photo # 2 –



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Ward and Son Operating - Loc ID 311869

Inspection Date: 05/06/2020



Photo # 3 – Fresh oil stained soil on the surface of the stockpile has been added since the 3/22/2019 inspection date photographs



Location Name: – Ward and Son Operating - Loc ID 311869

Inspection Date: 05/06/2020



Photo # 4 –



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources