

Inspection Photos
Location Name: BRIANNA 23-16
API#: 05-071-08709
INSP. #: 695102822



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: BRIANNA 23-16

API#: 05-071-08709

INSP. #: 695102822



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION (MISCELLANEOUS PIECES OF PIPES AND FITTING). REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f. CA DATE 8-14-20.

PHOTO 6: UNUSED EQUIPMENT STORED ON LOCATION (PUMPJACK, POWER UNIT FOR PUMPJACK AND LADER). REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f. CA DATE 8-14-20.

Inspection Photos

Location Name: BRIANNA 23-16

API#: 05-071-08709

INSP. #: 695102822



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION (1" RISER NEAR PUMPJACK PAD). REMOVE UNUSED EQUIPMENT COMPLY WITH NTO AND RULE 603.f. CA DATE 8-14-20.