

Inspection Photos  
Location Name: MORRISON 44-17  
API#: 05-071-08653  
INSP. #: 695102849




PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

**Inspection Photos**  
**Location Name: MORRISON 44-17**  
**API#: 05-071-08653**  
**INSP. #: 695102849**



**PHOTO 3: GAS METER CAL. REPORT**



**PHOTO 4: UNUSED EQUIPMENT (2" RISER). REMOVE  
 UNUSED EQUIPMENT COMPLY WITH NTO AND RULE 603.f.  
 CA DATE 8-14-20.**