

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2020

Submitted Date:

05/14/2020

Document Number:

696102969**FIELD INSPECTION FORM**Loc ID 323456 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245265	WELL	PR	09/01/2019	GW	123-13060	WEBSTER 9-28	PR

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Location ID (323456).
(Well(s): 1: Producing | PR).

Centralized Battery formerly served 1 Location ID (330263).
(Well(s): 1: Plugged & Abandoned | PA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:	Centralized Battery serves 1 Location ID (323456). (Well(s): 1: Producing PR). Centralized Battery formerly served 1 Location ID (330263). (Well(s): 1: Plugged & Abandoned PA).					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:						

Paint

Condition					
Other (Content)					
Other (Capacity)	48 Bbls.				
Other (Type)					

Berms

Inspector Name: Evins, Bret

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares berms w/ crude oil tanks.					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	OTHER	STEEL AST		40.455437,-104.550626	
Comment: Equalizer line connects crude oil tanks.						
Corrective Action:				Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 Bbls.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares berms w/ produced H2O tank.					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	245265	Type:	WELL	API Number:	123-13060	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 05/13/2020 at approximately 15:02 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WEBSTER-66N64W /28NESE Location ID: 323456 Well Name: Webster 9-28 API: 05-123-13060 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (323456). (Well(s): 1: Producing PR).</p> <p>Centralized Battery formerly served 1 Location ID (330263). (Well(s): 1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/14/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102970	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151291