

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/14/2020

Document Number:

696102973

FIELD INSPECTION FORM

Loc ID 420803 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420801	WELL	PR	07/01/2018	OW	123-32718	ROHR A 28-25	PR

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Location ID (420803).
(Well(s): 1: Producing | PR).

Centralized Battery formerly served 2 Location IDs (323398, 408144).
(Well(s): 2: Plugged & Abandoned | PA).

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 2		
Comment:	ECD scrubbers.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	ECD #1: Controls crude oil tanks VOCs. ECD #2: Controls separator VOCs. Pilots: ON.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 1 Location ID (420803). (Well(s): 1: Producing PR). Centralized Battery formerly served 2 Location IDs (323398, 408144). (Well(s): 2: Plugged & Abandoned PA).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,-104.557089
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Shares berms w/ produced H2O vault.		
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,

Comment:	
Corrective Action:	Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Shares berms w/ crude oil tank.		
Corrective Action:		Date:	

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 420801 Type: WELL API Number: 123-32718 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing | PR.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 05/13/2020 at approximately 15:45 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROHR USX A /28-25 Location ID: 420803 Well Name: Rohr A 28-25 API: 05-123-32718 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (420803). (Well(s): 1: Producing PR).</p> <p>Centralized Battery formerly served 2 Location IDs (323398, 408144). (Well(s): 2: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102974	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151295