

Inspection Photos

Location Name: MARALEX RESOURCES INC Domestic Tap /18SENW

Location ID: 475647



Photo #1192 Domestic tap off of sales line.



Photo #1194 Big joe regulator pressure plate.

Inspection Photos

Location Name: MARALEX RESOURCES INC Domestic Tap /18SENW

Location ID: 475647



Photo #1195 scrubber pot.



Photo #1193 Little joe regulator pressure plate.