

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S100W /13NESW

Location ID: 312573



Photo #1196 from entrance to location



Photo #1197 Multiple places with debris on location.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S100W /13NESW

Location ID: 312573



**Photo #1198 Multiple places with debris on location.**