

Inspection Photos
Location Name: Gill-Trindle #1
Location ID: 307100



Wellhead sign

Inspection Photos
Location Name: Gill-Trindle #1
Location ID: 307100



Trash on 4/9/2020



Trash on 5/18/2020

Inspection Photos
Location Name: Gill-Trindle #1
Location ID: 307100



Trash and unused equipment on 4/9/2020



Trash and unused equipment on 5/18/2020

Inspection Photos
Location Name: Gill-Trindle #1
Location ID: 307100



Unused equipment on 4/9/2020



Unused equipment on 5/18/2020