

Inspection Photos
Operator: Petrox
API#: 007-06278
Date: 5/15/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the well pad entrance facing westward. Revegetation is progressing, largely with wheatgrass. As dense cheatgrass is also observed, weed control and additional vegetation efforts may be warranted.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area vegetation comprised of open/cleared sagebrush shrubland with grasses such as western wheatgrass, James galleta, and forbs such as snakeweed.