

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2020

Submitted Date:

05/18/2020

Document Number:

689704722

**FIELD INSPECTION FORM**
 Loc ID 335184 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 210864      | WELL | PR     | 04/19/1990  | GW         | 045-06622 | ARCO GV 22-29     | PR          |
| 288039      | WELL | PR     | 07/25/2007  | GW         | 045-13155 | PUCKETT GM 434-29 | PR          |
| 288040      | WELL | PR     | 07/25/2007  | GW         | 045-13154 | PUCKETT GM 323-29 | PR          |
| 288041      | WELL | PR     | 07/25/2007  | GW         | 045-13153 | PUCKETT GM 343-29 | PR          |
| 288042      | WELL | PR     | 07/25/2007  | GW         | 045-13152 | PUCKETT GM 444-29 | PR          |
| 288043      | WELL | PR     | 07/25/2007  | GW         | 045-13151 | PUCKETT GM 443-29 | PR          |
| 288044      | WELL | PR     | 07/25/2007  | GW         | 045-13150 | PUCKETT GM 543-29 | PR          |
| 288045      | WELL | PR     | 07/25/2007  | GW         | 045-13149 | PUCKETT GM 333-29 | PR          |
| 288046      | WELL | PR     | 06/29/2008  | GW         | 045-13148 | PUCKETT GM 534-29 | PR          |
| 288047      | WELL | PR     | 07/25/2007  | GW         | 045-13147 | PUCKETT GM 33-29  | PR          |
| 288048      | WELL | PR     | 07/31/2008  | GW         | 045-13146 | PUCKETT GM 634-29 | PR          |
| 288049      | WELL | PR     | 07/25/2007  | GW         | 045-13145 | PUCKETT GM 423-29 | PR          |
| 288050      | WELL | PR     | 07/25/2007  | GW         | 045-13144 | PUCKETT GM 334-29 | PR          |
| 288051      | WELL | PR     | 07/12/2008  | GW         | 045-13143 | PUCKETT GM 34-29  | PR          |

**General Comment:**

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 |       |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | TRASH |       |  |
| Comment:           |       |       |  |
| Corrective Action: |       | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |      |  |                 |
|-----------------------------------|------|--|-----------------|
| <b>Equipment:</b>                 |      |  | corrective date |
| Type: Plunger Lift                | # 14 |  |                 |
| Comment:                          |      |  |                 |
| Corrective Action:                |      |  | Date:           |
| Type: Bird Protectors             | # 8  |  |                 |
| Comment:                          |      |  |                 |
| Corrective Action:                |      |  | Date:           |
| Type: Horizontal Heated Separator | # 14 |  |                 |
| Comment:                          |      |  |                 |
| Corrective Action:                |      |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 2 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 210864         | Type: | WELL | API Number: | 045-06622 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288039         | Type: | WELL | API Number: | 045-13155 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288040         | Type: | WELL | API Number: | 045-13154 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288041         | Type: | WELL | API Number: | 045-13153 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288042         | Type: | WELL | API Number: | 045-13152 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288043         | Type: | WELL | API Number: | 045-13151 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288044         | Type: | WELL | API Number: | 045-13150 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288045         | Type: | WELL | API Number: | 045-13149 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 288046 | Type: | WELL | API Number: | 045-13148 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 288047 | Type: | WELL | API Number: | 045-13147 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 288048 | Type: | WELL | API Number: | 045-13146 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 288049 | Type: | WELL | API Number: | 045-13145 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**

Comment:

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 288050 | Type: | WELL | API Number: | 045-13144 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 288051 | Type: | WELL | API Number: | 045-13143 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          | Pass            |                         |                       |               |                          |         |
|                  |                 | Check Dams              | Pass                  |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
|                  |                 | Culverts                | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 689704723    | Inspection 689704722 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153943</a> |