


Inspection Photos
Location Name: Stroh PC O 13-79 HN
Location ID: 428628



Battery sign



Wellhead

Inspection Photos
Location Name: Stroh PC O 13-79 HN
Location ID: 428628



Debris on 4/30/2020



Debris on 5/19/2020

Inspection Photos
Location Name: Stroh PC O 13-79 HN
Location ID: 428628



Unused equipment on 4/30/2020



Unused equipment on 5/19/2020

Inspection Photos
Location Name: Stroh PC O 13-79 HN
Location ID: 428628



Unused equipment on 4/30/2020



Unused equipment on 5/19/2020