

Inspection Photos
Operator: Southland Royalty
API#: 007-06183
Date: 5/15/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass and smooth brome.



Photos 3/4. View of musk thistles that appear to be herbicide treated within the project area.



Photo 5. View of reference area vegetation comprised of pinyon juniper woodland with understory of grasses and forbs such as Indian ricegrass, James galleta, and Navajo tea.