

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/19/2020

Submitted Date:

05/19/2020

Document Number:

700700729

FIELD INSPECTION FORM

Loc ID 334881	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10531 Name of Operator: GRIZZLY OPERATING LLC Address: 5847 SAN FELIPE #3000 City: HOUSTON State: TX Zip: 77057				Findings: 17 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211517	WELL	PR	07/16/2009	GW	045-07277	GIBSON GULCH UNIT 6-31	PR
211518	WELL	PR	12/27/2007	GW	045-07278	GIBSON GULCH UNIT 5-31	PR
211519	WELL	PR	07/16/2009	GW	045-07279	GIBSON GULCH UNIT 6-31 C	PR
260610	WELL	PR	07/16/2009	GW	045-07878	GIBSON GULCH UNIT 6-31D	PR
260611	WELL	PR	07/16/2009	GW	045-07879	GIBSON GULCH UNIT 11-31	PR
261023	WELL	PR	07/16/2009	GW	045-07924	GIBSON GULCH 12-31	PR
291170	WELL	PR	03/15/2008	GW	045-14314	GGU MILLER 12A-31-691	PR
291171	WELL	PR	03/27/2008	GW	045-14309	GGU MILLER 23C-31-691	PR
291172	WELL	PR	03/15/2008	GW	045-14310	GGU MILLER 13D-31-691	PR
291173	WELL	PR	03/15/2008	GW	045-14311	GGU MILLER 22A-31-691	PR
291174	WELL	PR	02/10/2008	GW	045-14312	GGU MILLER 22D-31-691	PR
291175	WELL	PR	03/15/2008	GW	045-14313	GGU MILLER 13C-31-691	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 5/19/20 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 6-31, at Location # 334881 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	IGNITOR/COMBUSTOR				
Comment:					
Corrective Action:				Date:	

Equipment:					corrective date
Type: Deadman # & Marked	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 11				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 12				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	500 gallon methanol tank				
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 12				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 4				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	HEATED STEEL AST		,	
Comment:	two (2) tanks are not heated					
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211517	Type:	WELL	API Number:	045-07277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	211518	Type:	WELL	API Number:	045-07278	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	211519	Type:	WELL	API Number:	045-07279	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	260610	Type:	WELL	API Number:	045-07878	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	260611	Type:	WELL	API Number:	045-07879	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	261023	Type:	WELL	API Number:	045-07924	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291170	Type:	WELL	API Number:	045-14314	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291171	Type:	WELL	API Number:	045-14309	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	291172	Type:	WELL	API Number:	045-14310	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	291173	Type:	WELL	API Number:	045-14311	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	291174	Type:	WELL	API Number:	045-14312	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	291175	Type:	WELL	API Number:	045-14313	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Ditches				
Gravel		Gravel				
Berms		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700735	photos for GGU 6-31	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154548