

Inspection Photos
Location Name:Thompson - Price #2
Location ID: 320156



Photo #1 tanks



Photo #2 stained soil next to PR Water

Inspection Photos
Location Name:Thompson - Price #2
Location ID: 320156



Photo #3 no bull plug in load out lines



Photo #4 vertical separator & EDC

Inspection Photos
Location Name: Thompson - Price #2
Location ID: 320156



Photo #5 Pump Jack



Photo #6 uncontained chemical barrels.

Inspection Photos
Location Name:Thompson - Price #2
Location ID: 320156



Photo #7 stained soil next to Pump Jack motor