

Inspection Photos  
Location Name: MARJO #M2  
API#: 05-071-40017  
INSP. #: 695102870



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/ ACCORDING TO COGCC RECORD THE WELL NAME IS MARJO #M2. **COMPLY WITH RULE 210.b. CA DATE 8-19-20**

Inspection Photos  
Location Name: MARJO #M2  
API#: 05-071-40017  
INSP. #: 695102870



**PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION  
(PIPE, METAL CONTAINMENT MATERIAL AND SKID STEAR).  
REMOVE OR INSTALL UNUSED EQUIPMENT, COMPLY WITH  
RULE 603.f. THIS IS SECOND NOTICE FOR THIS CA,  
CORRECTIVE ACTION IS THE DATE GIVEN ON ORIGINAL  
INSPECTION DOC#689901527**