

Interim Reclamation and Stormwater Inspection

May 18, 2020

Operator: WHITING OIL & GAS CORPORATION- #96155

Location ID: 317522

Inspection Document #: 697501526

Weld County, CO

NENE Section 12 T10N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NELSON RANCHES #4
Location ID: 317522



Photo 1. Photo taken from the well location, facing East. Photo illustrates temporary fencing is disrepair.

Inspection Photos
Location Name: NELSON RANCHES #4
Location ID: 317522



Photo 2. Photo taken from the well location, facing East. Photo illustrates barbed wire fencing in disrepair and a safety hazard (e.g., wildlife and livestock).

Inspection Photos
Location Name: NELSON RANCHES #4
Location ID: 317522



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.