

Inspection Photos

Loc#335172

Operator: Terra

Inspection Number: 692402192

Inspection Date: 5/14/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry and new fencing and alley.

May 14, 2020



Photo#2:
Interim at North side of Location.

May 14, 2020



Photo#3:
Interim at North side; hard packed area where equipment was stored.



Photo#4:
Interim at West side of Location.

Photo#5:
Interim at West side of Location.

May 14, 2020



Photo#6:
Wattles and subsidence repaired.



Photo#7:
Wattles and subsidence repaired.

May 14, 2020



Photo#8:
Debris weeds behind separators.



Photo#9:
Scotch thistle on site..

May 14, 2020