

URSA OPERATING COMPANY LLC  
BMC D PAD  
Location # 446582



Inspector Mike Longworth observed odor from entrance of location coming from the chemical containers at the well heads.

URSA OPERATING COMPANY LLC  
BMC D PAD  
Location # 446582



**Lid on one of the containers is cross treaded**

URSA OPERATING COMPANY LLC  
BMC D PAD  
Location # 446582



**Some spots of chemical in spill pan under chemical pumps.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

URSA OPERATING COMPANY LLC  
BMC D PAD  
Location # 446582



**Winds out of the south west.**