

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2020

Submitted Date:

05/19/2020

Document Number:

689704726

FIELD INSPECTION FORM

Loc ID: 446582
Inspector Name: LONGWORTH, MIKE
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 950 17TH STREET, SUITE 1900
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446573	WELL	PR	09/04/2018	GW	045-23262	BMC D 32C-18-07-95	PR
446574	WELL	PR	04/01/2018	GW	045-23263	BMC D 44D-07-07-95	PR
446575	WELL	PR	06/01/2018	GW	045-23264	BMC D 41C-18-07-95	PR
446576	WELL	PR	05/01/2018	GW	045-23265	BMC D 41A-18-07-95	PR
446577	WELL	PR	03/01/2018	GW	045-23266	BMC D 34B-07-07-95	PR
446578	WELL	PR	05/01/2018	GW	045-23267	BMC D 31A-18-07-95	PR
446579	WELL	PR	03/01/2018	GW	045-23268	BMC D 34C-07-07-95	PR
446580	WELL	PR	07/01/2018	GW	045-23269	BMC D 32A-18-07-95	PR
446581	WELL	PR	08/01/2018	GW	045-23270	BMC D 32B-18-07-95	PR
446583	WELL	PR	04/01/2018	GW	045-23271	BMC D 31B-18-07-95	PR
446584	WELL	PR	09/07/2018	GW	045-23272	BMC D 32D-18-07-95	PR
446585	WELL	PR	04/01/2018	GW	045-23273	BMC D 34D-07-07-95	PR
446586	WELL	PR	09/09/2018	GW	045-23274	BMC D 32E-18-07-95	PR
446587	WELL	PR	03/01/2018	GW	045-23275	BMC D 34A-07-07-95	PR
446588	WELL	PR	06/01/2018	GW	045-23276	BMC D 31C-18-07-95	PR
446589	WELL	PR	07/01/2018	GW	045-23277	BMC D 31D-18-07-95	PR
446765	WELL	PR	05/01/2018	GW	045-23278	BMC D 41B-18-07-95	PR
447694	WELL	PR	06/01/2018	GW	045-23307	BMC D 11C-18-07-95	PR
447696	WELL	PR	09/02/2018	GW	045-23308	BMC D 12C-18-07-95	PR
447697	WELL	PR	07/01/2018	GW	045-23309	BMC D 11D-18-07-95	PR

447699	WELL	PR	08/01/2018	GW	045-23311	BMC D 12B-18-07-95	PR
447700	WELL	PR	07/01/2018	GW	045-23312	BMC D 12A-18-07-95	PR
447701	WELL	PR	06/01/2018	GW	045-23313	BMC D 21C-18-07-95	PR
447702	WELL	PR	08/01/2018	GW	045-23314	BMC D 22B-18-07-95	PR
447703	WELL	PR	07/01/2018	GW	045-23315	BMC D 22A-18-07-95	PR
447704	WELL	PR	04/01/2018	GW	045-23316	BMC D 21B-18-07-95	PR
447705	WELL	PR	07/01/2018	GW	045-23317	BMC D 21D-18-07-95	PR
447714	WELL	PR	09/03/2018	GW	045-23326	BMC D 22C-18-07-95	PR

General Comment:

I, Inspector Mike Longworth, conducted an inspection on site in response of Complainants 18200448946, 18200448939, 18200448940 During this inspection the following possible compliance issues were observed:
 Inspector Mike Longworth observed odor from entrance of location coming from the chemical containers at the well heads. Winds out of the south west carrying chemical odor to the entrance in north east. Lid on one of the conainers is cross treaded and some spots of chemical in spill pan under chemical pumps.
 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
 C.A. Date 05/21/2020
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>446573</u>	Type: <u>WELL</u>	API Number: <u>045-23262</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Complaint

Comment:	Complaintants 18200448946, 18200448939, 18200448940 Inspector Mike Longworth observed odor from entrance of location coming from the chemical containers at the well heads. Winds out of the south west carrying chemical odor to the entrance in north east. Lid on one of the containers is cross treaded and some spots of chemical in spill pan under chemical pumps.
----------	--

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
--------------------	---

Date:	<u>05/21/2020</u>
-------	-------------------

Facility ID: <u>446574</u>	Type: <u>WELL</u>	API Number: <u>045-23263</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446575</u>	Type: <u>WELL</u>	API Number: <u>045-23264</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446576</u>	Type: <u>WELL</u>	API Number: <u>045-23265</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446577</u>	Type: <u>WELL</u>	API Number: <u>045-23266</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446578</u>	Type: <u>WELL</u>	API Number: <u>045-23267</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446579</u>	Type: <u>WELL</u>	API Number: <u>045-23268</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446580</u>	Type: <u>WELL</u>	API Number: <u>045-23269</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446581</u>	Type: <u>WELL</u>	API Number: <u>045-23270</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446583</u>	Type: <u>WELL</u>	API Number: <u>045-23271</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446584</u>	Type: <u>WELL</u>	API Number: <u>045-23272</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446585</u>	Type: <u>WELL</u>	API Number: <u>045-23273</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446586</u>	Type: <u>WELL</u>	API Number: <u>045-23274</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446587</u>	Type: <u>WELL</u>	API Number: <u>045-23275</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446588</u>	Type: <u>WELL</u>	API Number: <u>045-23276</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446589</u>	Type: <u>WELL</u>	API Number: <u>045-23277</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>446765</u>	Type: <u>WELL</u>	API Number: <u>045-23278</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>447694</u>	Type: <u>WELL</u>	API Number: <u>045-23307</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447696</u>	Type: <u>WELL</u>	API Number: <u>045-23308</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447697</u>	Type: <u>WELL</u>	API Number: <u>045-23309</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447699</u>	Type: <u>WELL</u>	API Number: <u>045-23311</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447700</u>	Type: <u>WELL</u>	API Number: <u>045-23312</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447701</u>	Type: <u>WELL</u>	API Number: <u>045-23313</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447702</u>	Type: <u>WELL</u>	API Number: <u>045-23314</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447703</u>	Type: <u>WELL</u>	API Number: <u>045-23315</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447704</u>	Type: <u>WELL</u>	API Number: <u>045-23316</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447705</u>	Type: <u>WELL</u>	API Number: <u>045-23317</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>447714</u>	Type: <u>WELL</u>	API Number: <u>045-23326</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704727	Inspection 689704726 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155072