

# *Inspection Photo*

*ALs Loc#419862*

*Operator: Terra*

*Inspection Number: 692402191*

*Inspection Date: 5/14/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Unused equipment on location: flowlines & Risers.

May 14, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Mead ALs Loc#419862