

Inspection Photos
Location Name: #1 Lois Gillette
Location ID: 332312



Photo 1 – Wellhead Sign



Photo 2 – Wellhead

Inspection Photos
Location Name: #1 Lois Gillette
Location ID: 332312



Photo 3 – Tubing Gauge



Photo 4 – Casing Gauge

Inspection Photos
Location Name: #1 Lois Gillette
Location ID: 332312



Photo 5 – No wildlife netting on Containment



Photo 6 – Unused pipe