

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 3: Wellhead Sign



Photo 4: Wellhead



Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 7: Wellhead



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 9: Wellhead



Photo 10: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917




Photo 11: Wellhead



Photo 12: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917




Photo 13: Wellhead



Photo 14: Wellhead Sign



Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 15: Wellhead



Photo 16: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 17: Wellhead



Photo 18: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 19: Wellhead



Photo 20: Wellhead



Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 21: Wellhead



Photo 22: Wellhead Sign



Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Colorado Oil and Gas Conservation Commission
40.46295, -104.9274, 1443.5m, 352°
May 20, 2020 11:08:55

Photo 23: Wellhead



Colorado Oil and Gas Conservation Commission
40.46297, -104.92737, 1442.3m, 352°
May 20, 2020 11:09:05

Photo 24: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 25: Wellhead



Photo 26: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 27: Wellhead



Photo 28: Wellhead Sign

Inspection Photos
Location Name: Raindance FD 19-219HN
Location ID: 427917



Photo 29: Wellhead



Photo 30: Tanks appear to not be grounded