

# *Inspection Photo*

*Loc#335048*

*Operator: Terra*

*Inspection Number: 692402198*

*Inspection Date: 5/15/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location; Vac truck backed up to excavation.

May 15, 2020



Photo#2:  
Excavation exposing old lines.

May 15, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra McClung Loc#335048



**Photo#3:**

Interim at South side, of Location; insert of NW portion of Interim where Mullein is of concern.

May 15, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra McClung Loc#335048



Photo#4:  
Installing new line.

May 15, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra McClung Loc#335048