

**Inspection Photos**  
**Location Name: BCU 150 Pad**  
**Location ID: 334554**  
**Inspection Date: May 12, 2020**



**Location sign**



**Tank battery**



**Inspection Photos**  
**Location Name: BCU 150 Pad**  
**Location ID: 334554**  
**Inspection Date: May 12, 2020**



**Unmarked riser**



**Pump house**





**Inspection Photos**  
**Location Name: BCU 150 Pad**  
**Location ID: 334554**  
**Inspection Date: May 12, 2020**



**Damaged pump house liner**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources