

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 3 TB sign

Photo 4 TB, stained soil by load out line

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302




Photo 5 Stained soil by load out line

Photo 6 bird protector lying on the ground next to Horiz.
Heated Sep.

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 7 gas meter run



Photo 8 Horizontal Heated Separator/ bird protector is missing

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302




Photo 9 Vertical Separator