

Water Well Analysis

Well Name	API No.	Lat	Long	Gas Well Elevation	Top Perf	Bottom Perf	Well Description	Receipt	Permit #	Depth	GS Elevation	Bottom Hole Elevation	Horizontal Distance (ft)
Rush Hour 24-2	05-071-09587	37.28338	-104.85956	7612	1256	3011	Schultz, Frank A	9089624	90109	53	7591	7538	260
							Manzanaras, Tony	9089490	79686	96	7629	7533	552
							Schultz, Frank A	9089622	90107	65	7615	7550	5031
							Schultz, Frank A	9089623	90108	100	7472	7372	4090
							Valentine June & August	9089156	27735	87	7723	7636	2967
							Valentine Ranch LLC	3677100	303961	200	7595	7395	4715
							Schultz, Frank A	9089625	90110	40	7810	7770	3892

