

Inspection Photo

Loc#335487

Operator: Terra

Inspection Number: 692402193

Inspection Date: 5/14/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Well location and thought to be, remote two tier location housing Tanks and separators.

May 14, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Potter Loc#335487



Photo#2:
Heavily utilized Interim area.



Photo#3:
Heavily utilized Interim area & Russian Olive.

May 14, 2020



Photo#4:
Down fence at well line up.



Photo#5:
Down fence at well line up.

May 14, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Potter Loc#335487