

Inspection Photos

API: 071-07705

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/20/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 1. Facing west along the reclaimed access road. The desirable vegetation is uniformly established along the former road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 2. Facing west along the reclaimed road toward the location. The fencing material previously observed in this area has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 3. Facing west at the location. The desirable vegetation is uniformly established in this portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 5. Facing northeast at the west side of the location. This area consists predominately of undesirable weeds (*Kochia* sp.). This appears to be the former area of the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 6. Facing southwest at the west side of the location. This area consists predominately of undesirable weeds (*Kochia* sp.). This appears to be the former area of the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020

Inspection Photos



Photo 7. Facing northwest toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 5/20/2020