

# Inspection Photos

API: 071-07515

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/20/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020

## Inspection Photos



**Photo 1.** Facing northeast toward the location. A perimeter fence is installed around the location. The wire gate in this photo needs maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 2.** Facing east at the southern portion of the location. The dark green vegetation is predominately undesirable weeds (Russian thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 3.** Facing northwest at the southern portion of the location. The dark green vegetation is predominately undesirable weeds (Russian thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 4.** Facing north at eastern side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 5.** Facing northwest at the northern portion of the location. The dark green vegetation is predominately undesirable weeds (Russian thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 6.** Facing southeast at the northern portion of the location. The dark green vegetation is predominately undesirable weeds (Russian thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 7.** View of undesirable weed vegetation which is Russian thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 8.** The area at the center of the location consist of desirable native vegetation species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020



## Inspection Photos



**Photo 9.** Facing north toward the surrounding undisturbed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 5/20/2020