

**Inspection Photos**  
**Location Name: Farm Ranch Exploration #1**  
**Location ID: 319972**



**Photo #1 tanks**



**Photo #2 Pump Jack**

**Inspection Photos**  
**Location Name: Farm Ranch Exploration #1**  
**Location ID: 319972**



**Photo #3 Separator and EDC**

**Photo #4 Equipment trailer with steel pipe**

Inspection Photos  
Location Name: Farm Ranch Exploration #1  
Location ID: 319972



Photo #5 Unused equipment around separator house and EDC

Photo #6 Unused equipment around separator house and EDC

**Inspection Photos**  
**Location Name: Farm Ranch Exploration #1**  
**Location ID: 319972**



**Photo #7 stained soil on west side of separator**

**Photo #8 Bull Plug missing from load out line**