

# *Inspection Photo*

*Loc#323973*

*Operator: Terra*

*Inspection Number: 692402197*

*Inspection Date: 5/14/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 14, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Savage Loc#323973





Photo#2:  
BMPs that need maintenance and Debris Weeds.

May 14, 2020



Photo#3:  
BMPs that need maintenance and Debris Weeds



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Savage Loc#323973





Photo#4:  
Anchor Marker down.

May 14, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#5:  
Showing heavily impacted Interim area.

Inspection Photos: Terra Savage Loc#323973