

Inspection Photos

Location Name: MGP A-3 FOLLOW UP

API#: 05-071-06093

INSP. #: 695102875




PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: MGP A-3 FOLLOW UP
API#: 05-071-06093
INSP. #: 695102875



Colorado Oil & Gas Conservation Commission
37.10592, -104.7835, 2024.0m, 218°
2020/05/22 10:02:25



Colorado Oil & Gas Conservation Commission
37.1058, -104.78341, 2016.0m, 207°
2020/05/22 10:01:20

PHOTO 3: GAS METER CAL. REPORT

PHOTO 4: FREEBOARD MARKER IS NOT INSTALLED ACCORDING TO THE RULE (THE MARKER HAS TO BE INSTALLED ON THE LOWEST ELEVATION SIDE OF PIT MEASURED FROM ORIGINAL GROUND LEVEL, NOT THE TIP OF THE BERM). **COMPLY WITH RULE 902.b. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, CA DATE IS THE ORIGINAL CA DATE FROM PREVIOUS INSPECTION DOC#695100198.**

Inspection Photos

Location Name: MGP A-3 FOLLOW UP

API#: 05-071-06093

INSP. #: 695102875



PHOTO 5: UNUSED EQUIPMENT (1" RISER NEAR PUMPJACK).
REMOVE UNUSED EQUIPMENT ACCORDING TO NTO AND
RULE 603.f.. CA DATE 8-22-20.



PHOTO 6: UNUSED EQUIPMENT STORED ON LOCATION.
REMOVE OR INSTALL UNUSED EQUIPMENT. COMPLY WITH
RULE 603.f. CA DATE 8-22-20

