

Inspection Photos  
Location Name: Suckla G unit #1  
Location ID: 317830



Photo 1 WH sign

Photo 2 WH

**Inspection Photos**  
**Location Name: Suckla G unit #1**  
**Location ID: 317830**



**Photo 3 PU**

**Photo 4 transformers, meter box and electric panel**

**Inspection Photos**  
**Location Name: Suckla G unit #1**  
**Location ID: 317830**



**Photo 5 Location**

**Photo 6 Gas meter run**

**Inspection Photos**  
**Location Name: Suckla G unit #1**  
**Location ID: 317830**



**Photo 7 Flow line manifold**

**Photo 8 Horizontal Heated Separator**

Inspection Photos  
Location Name: Suckla G unit #1  
Location ID: 317830




Photo 9 TB sign

Photo 10 TB

Inspection Photos  
Location Name: Suckla G unit #1  
Location ID: 317830



Photo 11 stained soil under split load out valve

Photo 12 Stained soil by load out line